

EyeCap Installation flow chart

Installation Guide

How to install EyeCap?



① termination materials (cable, terminal, EyeCap)



② Mark on cable for removing cable sheath



③ Cut the lag of cable



④ Remove the sheath of cable



⑧ Slip cap into lug



⑦ Clamping completed



⑥ Clamp on lug



⑤ Slip Cap into Cable




We recommend the transparent part is placed at the end of the cable, unlike the above photo, even it can be freely placed, case by case, depending on which parts is sensitive to overheat.

Maintenance & replacement

Replacement guide - **No Cable Cutting**

You do not need to cut the cable, you can replace it readily with EyeCap



Replacement flow chart : **Sleeve-on direction**

