ACN 070 053 584

23-25 Production Ave Molendinar, Queensland, 4214 Australia

#### ABN 39 070 053 584

Phone 07 55949844 Fax 07 55949079 Email sales@rg.com.au

# SERVICE BULLETIN

Rev. No.	Date	Author	Description
Original issue	5 December, 2017	Andrew Danks	TF Basket upgrade

#### **MACHINE OR VEHICLE AFFECTED:**

TF Model MEWPs with TL basket retro-fit.

#### **RISK IDENTIFIED:**


Weld joint failure.

#### **DESCRIPTION:**

Rotating basket cylinder anchor point weld failure.

### INSPECTION REQUIREMENT DURING 3 MONTHLY INSPECTION:

- Raise boom to access underside of the basket.
- Remove under-basket cover and inspect Item 8 check that it is secure. If it is loose or out of square with the base plate, it will need to be repaired.



## **CUSTOMER ACTION REQUIRED:**

MEWP owners must circulate this bulletin to all their maintenance personnel.

## **RG ACTION REQUIRED:**

A detailed repair procedure is available from Redmond Gary Australia, on request.

Please contact Peter Danks, our Service & Spare Parts Supervisor, on (07) 5594 9844, if further information is required.

Andrew Danks Managing Director

