

# SERVICE BULLETIN

Rev. No.	Date	Author	Description
Original issue	19 February, 2018	Andrew Danks	2.5t SLCT

## MACHINE OR VEHICLE AFFECTED:

2.5t SLCT up to and including SN 11127.

## RISK IDENTIFIED:

Potential Damage to Roller Bearing.

## DESCRIPTION:

The roller bearing potentially suffers damage due to handling of the spindle shaft.

## SPINDLE HANDLING INSTRUCTIONS:

Keep spindle horizontal during disengagement with drum and spindle bearing housing as much as possible to avoid damage to the bearing seal and bearing.

If the spindle needs to be lowered to the ground please assure to completely remove it from both bearing housings and put it onto the ground separately.



**CUSTOMER ACTION REQUIRED:**

Follow instructions!

**RG ACTION REQUIRED:**

Please contact Peter Danks, our Service & Spare Parts Supervisor, on (07) 5594 9844, if further information is required.

Andrew Danks  
Managing Director