



# SET UP THROTTLE CONTROL

DOCNUMBER  
Rev. 00  
03/10/2023  
Page 1 of 1

REVISIONS			RESPONSIBLE	
N.	DATE	DESCRIPTION	CREATED BY	CHECK/APPROVE
1	05/10/23	Original	Snehal Rana	

## Set Up For Throttle Control:

1. Connect power supply negative to pin 1 and negative on volt meter
2. Connect +5v from power supply to pin 5.
3. Connect positive lead from voltmeter to pin 2 and set to 24v DC.
4. Connect +24v to pin 3. There should be a 2 to 3 second delay before a change in voltage on the meter is seen.
5. Adjust input 2 output adjustment to get a reading for 1.10v.
6. Adjust input 2 output adjustment to get a reading of 1.35v.
7. Disconnect, reconnect and check.

