

**ACN 070 053 584**

23-25 Production Ave  
Molendinar, Queensland, 4214  
Australia

**ABN 39 070 053 584**

Phone 07 55949844  
Fax 07 55949079  
Email sales@rg.com.au

# SERVICE BULLETIN

## 30<sup>th</sup> April, 2010


### LABEL POSITIONS FOR EWP FLY BOOM

Pictured below is EWP Model TF17M as delivered April, 2010. You will note there are no labels on the fly boom in the area between the insulation markers. This is a requirement of **AS1418.10 (Int.)-2004. Section 1.12.5.17.2 Insulator location identifiers** - that states labels should not be applied to the insulated insert surface.

Any labels that were originally placed on the fly boom insulator have been relocated onto the top of the jackleg on the right hand side and cabinet work directly in front of that jackleg. (Please refer to photos below indicating new location of labels).



**LABELS LOCATED ON TOP OF RIGHT HAND JACKLEG AND CABINET WORK DIRECTLY IN FRONT OF THE JACKLEG.**



Close up photo of labels